

Weekly Update 10/31/19



Some of you may have noticed that the roof over the current sanctuary is not looking its best. We are using the opportunity of our construction to do some much-needed repairs in a few places, including the roof. The above picture shows two things worth noting – the replacement of our current roof and the removal of the overhang next to the North Wing. The latter work is in preparation for enclosing the walkway that will lead from our Grand Foyer to the Small Sanctuary. (There will be an interior corridor that goes right along the North Wing, located where the workers recently poured a concrete path.) If you are in our Grand Foyer, or as you can see in the picture below, the construction crew has installed a support structure in anticipation of making the physical connection between our Grand Foyer and the corridor. Making this connection will necessitate removing the currently blocked windows and creating a doorway in this location.



The rendering below may help you visualize what this corridor will look like from the outside. The corridor is behind the windows on the left side of the rendering. It will be great to see the rendering (which is from three years ago!) become a reality!




Temple Rodef Shalom

Entry to
Small Sanctuary
2014.09.06


Brawer & Hauptman

If you have any questions about the building project, feel free to email us at bptf@templerodefshalom.org